

Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Photo No.

Date: 08/06/2015

Direction Photo Taken:

Southwest

Description:

Animas River from U.S. Highway 550 southwest of Silverton



Photo No.

Date: 08/06/2015

Direction Photo Taken:

West



Page 1 of 19



Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Animas River from U.S. Highway 550 southwest of Silverton

Photo No.

Date: 08/06/2015

Direction Photo Taken:

Northwest

Description:

Animas River from U.S. Highway 550 southwest of Silverton.




Photo No.

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Repairing road damage along County Road 110 between Silverton and Gladstone.

Photo No.

Date: 08/06/2015

Direction Photo Taken: South

Description:

Repairing road damage along County Road 110 between Silverton and Gladstone.




Photo No.

6

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Road crossing over Cement Creek at Gladstone damaged, view from downstream.

Phot o No.

Date: 08/06/2015

Direction Photo Taken:

North

Description:

Upstream of Cement Creek culvert at Gladstone.



Photo No.

8

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Road at Gladstone coned off.

Photo No.

Date: 08/06/2015

Direction Photo Taken:

South

Description:

Cement Creek and North Fork convergence after Gold King discharge.



Photo No.

10

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Cement Creek and North Fork convergence after Gold King discharge.

Photo No. 11

Date: 08/06/2015

Direction Photo Taken:

East

Description:

Damaged GSA Suburban at base of Gold King mine dump




Photo No. 12

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Temporary culvert for North Fork Cement Creek at road at base of Gold King mine dump.

Photo No. 13

Date: 08/06/2015

Direction Photo Taken:

West

Description:

Temporary road crossing at base of Gold King mine dump.



Photo No. 14

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Gold King mine dump damage.

Photo No. 15

Date: 08/06/2015

Direction Photo Taken:

West

Description:

Gold King mine dump damage.



Photo No. 16

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Gold King mine dump damage.

Photo No. 17

Date: 08/06/2015

Direction Photo Taken:

Northwest

Description:

Gold King mine dump damage.



Photo No. 18

Date: 08/06/2015

Direction Photo

Taken:

Northwest





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Gold King mine dump damage.

Photo No. 19

Date: 08/06/2015

Direction Photo Taken:

North

Description:

Gold King mine dump damage.




Photo No.

20

Date: 08/06/2015

Direction Photo Taken:

Southwest





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

North Fork Cement Creek downstream of Gold King road crossing. North Fork Cement Creek is orange.

Photo No. 21

Date: 08/06/2015

Direction Photo Taken:

West

Description:

Switchback at the Gold King King access road.



Photo No. 22

Date: 08/06/2015

Direction Photo Taken:

West





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Gold King mine dump road damage.

Photo No. 23

Date: 08/06/2015

Direction Photo Taken:

East

Description:

Gold King mine dump damage.



Photo No.

24

Date: 08/06/2015

Direction Photo Taken:

East





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Top of Gold King Mine Dump.

Photo No. 25

Date: 08/06/2015

Direction Photo Taken:

Northeast

Description:

Gold King adit post discharge.




Photo No.

26

Date: 08/06/2015

Direction Photo Taken:

iancii





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Gold King adit post discharge.

Photo No. 27

Date: 08/06/2015

Direction Photo Taken:

North

Description:

Gold King adit




Photo No.

28

Date: 08/06/2015

Direction Photo Taken:

East





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Channalized flow to edge of mine dump.

Photo No. 29

Date: 08/06/2015

Direction Photo Taken:

West

Description:

Horiba Readings stabilizing in adit discharge. pH 3.41




Photo No.

Date: 08/06/2015

30

Direction Photo Taken:

West





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Stabilized Horiba readings (DO is not accurate). pH = 2.93 Turbidity too high for sensor reading so display shows 0 NTU.

Photo No. 31

Date: 08/06/2015

Direction Photo Taken:

Northwest

Description:

Secondary sealed adit at Gold King, flow has decreased from 10's of gallons per minute to almost 0.



Photo No.

32

Date: 08/06/2015

Direction Photo Taken:

West/Down





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Overview of the Gold King waste dump pad after mine discharge. Note orange water in half culvert channel and damage to center of pad.

Photo No.

Date: 08/06/2015

Direction Photo Taken:

West

Description:

Overview of the Gold King Post mine discharge.



Photo No. 34

Date: 08/06/2015

Direction Photo Taken:

West and downhill





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Overview of the Gold King mine dump after mine discharge.

Photo No. 35

Date: 08/06/2015

Direction Photo Taken:

West/Down

Description:

Overview of the Gold King mine dump after mine discharge.




Photo No. 36

Date: 08/06/2015

Direction Photo Taken:





Project Name:

Gold King Mine ER

Site Location:

Silverton, San Juan County, Colorado

Project No.

20408.012.001.0267.0

Description:

Horiba reading of Cement Creek upstream of North Fork confluence. Bad DO reading. pH = 5.04

Photo No. 37

Date: 08/06/2015

Direction Photo Taken:

North

Description:

Stabilized Horiba reading of Cement Creek north of Gladstone culvert. Bad DO reading, pH = 2.98




Photo No.

Date: 08/06/2015

38

Direction Photo Taken:





Project Name:	Site Location:	Project No.
Gold King Mine ER	Silverton, San Juan County, Colorado	20408.012.001.0267.0
Description:		
Updated view of road repair between Gladstone and Silverton.		